Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION Work Order Name: WO/60006EA9520/1 Work Order Type: Weatherization Audit Name: 60006EA9520 **CLIENT INFORMATION** Client Name: N/A Address: Client ID: 60006EA9520 Alt. Client ID: UNION **CLIENT CONTACT INFORMATION** N/A Applicant/Person of Site Built Record <u>AGENCY INFORMATION</u> Agency: East Tennessee Human Resource Agency **Agency Phone:** Address: Fax: **Email Address:** Company Name & License Number:

Contractor's Signature:

COMMENT

Client Name: N/A
Client ID: 60006EA9520
Alt. Client ID: UNION

Work Order (Bid Form)
Work Order Name: WO/60006EA9520/1

DOE Weatherization Assistant Version 8.5.0

Page 1 of 4

Report Run On: 5/6/2010

Measures

Measure 1 Ceiling Repair (SF)				Components					Inspected	
C		ceiling fan sheetrock 7"X d white paint	7" Bedroo	m # 2						
		•			Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
	Other		SqFt	1						
C	Other Detail									
Г										
				Measur	e Sub Total:			Sub Total:		
ſ	Field Notes:				-					
	c omment Most ve Foam d	tration Redctn Ints were covered by furn Irain holes in water line hor Ir strip Door # DR 2		ık cabir	Component	its			Inspected	
					Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
10	Miscellaneous Supplies	Infiltration Reduction	Each	1						
C	Other Detail						_			
				Measur	Measure Sub Total:		Sub Total:			
	Field Notes:									

Report Run On: 5/6/2010

Comment	/H Tank Insulation			Componen	ts		ı	Inspecte
			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Hot Water Equipment	DHW Tank Insulation	Each	1					
2 Labor	DHW Tank Insulation	Each	1					
Other Detail								
] []		
			Measur	e Sub Total:]	Sub Total:		
	/H Pipe Insulation			Componen				Inspecte
Comment	•	Units	Otv	Estimated	<u> </u>	Otv	Actual	
Comment # Material / Labor	Description / Comment	<i>Units</i> Each	Qty 1	•		Qty		Inspecte
Comment # Material / Labor	•			Estimated	<u> </u>	Qty	Actual	
Comment # Material / Labor 1 Insulation	Description / Comment DHW Pipe Insulation			Estimated	<u> </u>	Qty	Actual	
Comment # Material / Labor 1 Insulation	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	1	Estimated	<u> </u>	Qty	Actual	
# Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	1	Estimated	<u> </u>	Qty	Actual	
# Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	1	Estimated	<u> </u>		Actual	
# Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation cost for 10' of wrap	Each	1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Report Run On: 5/6/2010

Measure 5 Floor Ins. R-19				Components FD1					
Comment									
				Estimated	1	Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1914						
Other Detail									
				Measure Sub Total:			Sub Total:		
Field Notes:									
		Work O	rder Gra	nd Total:		Gran	d Total:		
		WORK OF	ruer Gra	nu rotai.		Gran	d Total.		